

Digital Service Record

The following services have been recorded for

Vehicle: CR-V
VIN: SHSRE6780DU020454
Date: August 8, 2026

Service Date	Mileage	Service performed	Performed by	
June 4, 2013	25 km	Pre Delivery Inspection		Michen GmbH Hauptstraße 2a 08301 Bad Schlema Germany
June 18, 2014	20063 km	Maintenance		Michen GmbH Hauptstraße 2a 08301 Bad Schlema Germany

Work Item	Status	Comment
1. A Oil and Oil filter Change		
2. B Maintenance		
3. BP Inspect vehicle corrosion		
*1: If item B appears before one year has checked passed, inspect for vehicle corrosion every year.		
External paintwork and panel corrosion check	checked	
Under body corrosion check	checked	

Additional Remarks :

May 13, 2015

35733 km

Maintenance



Michen GmbH
Hauptstraße 2a
08301 Bad Schlema
Germany

Work Item	Status	Comment
1. Replace dust and pollen filter		
2. A Oil and Oil filter Change		

3. B Maintenance

Additional Remarks :

April 13, 2016

48820 km

Maintenance



Michen GmbH
Hauptstraße 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **Inspect drive belt/s**
2. **7 Replace brake fluid**
3. **A Oil and Oil filter Change**
4. **B Maintenance**
5. **BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked
passed, inspect for vehicle corrosion
every year.

External paintwork and panel corrosion checked
check

Under body corrosion check checked

Additional Remarks :

June 29, 2016

51733 km

Maintenance



Michen GmbH
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **Regular MOT**

Additional Remarks :

January 4, 2017

60300 km

Maintenance



Michen GmbH
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **8 Replace engine air filter**
2. **8 Replace engine air filter**

Additional Remarks :

February 7, 2018

63164 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **A Oil and Oil filter Change**2. **B Maintenance**3. **BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked
passed, inspect for vehicle corrosion
every year.

External paintwork and panel corrosion checked
check

Under body corrosion check checked

Additional Remarks :

June 12, 2018

88209 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **Regular MOT**

Additional Remarks :

February 27, 2019

102969 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. **Replace dust and pollen filter**2. **Inspect drive belt/s**3. **Replace fuel filter**4. **7 Replace brake fluid**5. **8 Replace engine air filter**6. **A Oil and Oil filter Change**

7. B Maintenance**8. 8 Replace engine air filter****9. BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked passed, inspect for vehicle corrosion every year.

External paintwork and panel corrosion checked check

Under body corrosion check checked

Additional Remarks :

January 15, 2020

117901 km

Maintenance



Michen GmbH
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. A Oil and Oil filter Change**2. B Maintenance****3. BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked passed, inspect for vehicle corrosion every year.

External paintwork and panel corrosion checked check

Under body corrosion check checked

Additional Remarks :

February 19, 2020

120330 km

Maintenance



Michen GmbH
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. 3 Replace transmission fluid**2. 6 Replace rear differential oil****3. 8 Replace engine air filter****4. 8 Replace engine air filter**

Additional Remarks :

June 9, 2020

123480 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. Regular MOT

Additional Remarks :

January 13, 2021

133933 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. Replace dust and pollen filter**2. Inspect drive belt/s****3. A Oil and Oil filter Change****4. B Maintenance****5. BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked
passed, inspect for vehicle corrosion
every year.

External paintwork and panel corrosion checked
check

Under body corrosion check checked

Additional Remarks :

January 12, 2022

148936 km

Maintenance

**Michen GmbH**
Hauptstr. 2a
08301 Bad Schlema
Germany

Work Item

Status

Comment

1. Replace fuel filter**2. Inspect idle speed****3. 7 Replace brake fluid****4. A Oil and Oil filter Change****5. B Maintenance**

6. **BP Inspect vehicle corrosion**

*1: If item B appears before one year has checked
passed, inspect for vehicle corrosion
every year.

External paintwork and panel corrosion checked
check

Under body corrosion check checked
